

State of Utah

GARY R. HERBERT Governor

GREG BELL Lieutenant Governor Department of Environmental Quality

Amanda Smith Executive Director

DIVISION OF WATER QUALITY Walter L. Baker, P.E. Director C/007/006 Intoming C/007/038 CC: Kevin April

June 15, 2010

Mr. Dennis Ware, Environmental Coordinator Plateau Mining Corp. PO Box 30 Helper, Utah 84526

Subject:

Final Reconnaissance Inspection for UPDES Permit No. UTG040012 - Plateau Mining's

Crandall Canyon and Star Point Reclamation Sites.

Dear Mr. Ware:

As you know, on June 8, 2010 I met with you and members of DOGM, BLM and OSM and conducted a final reconnaissance inspection with regards to the former Crandall Canyon and Star Point mine facilities and UPDES Permit No. UTG040012. Specifically I observed the reclaimed areas and receiving water drainages. No deficiencies were observed and no response is required at this time. As noted in this inspection report, as well as in previous correspondences, the outfalls have been inactivated and DMRs will not need to be submitted so long as the potential to discharge remains obviated. Should conditions change at these facilities to include the need to discharge, please contact our offices to re-activate your permit status and include any outfall information as appropriate.

Enclosed is a copy of the inspection report for your records. I have appreciated your compliance efforts and in keeping me informed of the operations over the past several years. If you have any questions, please contact me at my new phone number (801) 536-4395 or by e-mail at jstudenka@utah.gov. Also, please note below our new address for any future mailings.

Sincerely,

Jeff Studenka, Environmental Scientist

Studenta

UPDES IES Section

Enclosures

cc (w/encl):

Amy Clark, EPA Region VIII

Claron Bjork, SE District Health Department

Dave Ariotti, SE District Engineer

Daron Haddock, Division of Oil Gas & Mines

RECEIVED

JUN 2 ! 2019

F:\wp\GP-Coal Mines\Plateau Mining\RI Final 6-8-2010 cov.ltr.doc

DIV OF OIL, GAS & AUNING



United States Environmental Protection Agency Washington, D.C. 20460

Water Compliance Inspection Report

Section A: Nationa	al Data System Coding (i.e.,	ICIS)		
Transaction Code NPDES U T G 0 4 0 0 1 2 3 11	yr/mo/day 1 0 0 6 0 8 12 1	Inspection Ty R R 18	e Inspector Fac. Type S 19 20	
Inspection Work Days Facility Self-Monitoring Evaluation Rating	BI QA		Reserved	
1 67 69 5 70	71 72	73 74	75 80	
Sect	ion B: Facility Data			
Name and Location of Facility Inspected (For industrial users discharging to POTW, also include POTW name and NPDES permit number) Plateau Mining Corp., Crandall Canyon & Star Point Mine Reclamation Sites:		9:05 am /6-8-2010	Permit Effective Date 5-1-2008	
Crandall Canyon site ~5 miles north of Helper, Utah off US 6 HWY in Car Star Point site in Wattis, UT off Hwy. 122 in Carbon County	rbon County	Exit Time/ Date 1:45 pm /6-8-2010	Permit Expiration Date 4-30-2013	
Name(s) of On-Site Representative(s)/Title(s)/Phone and Fax Number(s)		Other Facility Data (e.	, SIC NAICS, and other	
Dennis Ware, Environmental Coordinator Plateau Mining Corp. (435) 472-0475	descriptive information			
Name, Address of Responsible Official/Title/Phone and Fax Number Dennis Ware, Environmental Coordinator Plateau Mining Corp., Willow Creek Mine PO Box 30 Helper, UT 84526 (435) 472-0475	Contacted Yes No			
Section C: Areas Evaluated Dur	ing Inspection (Check only to	hose areas evaluated)	
Permit				
Section D: Su (Attach additional sheets of narrative and ch	mmary of Findings/Commer ecklists, including Single Eve	nts ent Violation codes, i	is necessary)	
SEV Codes SEV Description				
Name(s) and Signature(s) of Inspector(s)	Agency/Office/Phone and Fax Num	nber(s)	Date:	
JEFF STUDENKA, ENVIRONMENTAL SCIENTIST	DWQ (801) 536-4395		6-15-2010	
N/A	A A			
Name and Signature of Management Q A Reviewer	Agency/Office/Phone and Fax Number(s)		Date:	
MIKE HERKIMER, MANAGER UPDES IES SECTION MIKE HERKIMER, MANAGER UPDES IES SECTION MIKE HERKIMER, MANAGER UPDES IES SECTION	DWQ (801) 536-4390		6/15/10	
EPA Form 3560-3 (Rev 1-06) Previous editions are obsolete	Agency/Office/Phone and Fax Number(s) Date: DWQ (801) 536-4390 6/15/10			

INSPECTION PROTOCOL

UPDES Permit #: UTG040012 – Plateau Mining Corp.

Inspection Type: Reconnaissance Inspection (Final Reclamation)

Inspection Date: June 8, 2010

Weather Conditions: Sunny and warm, ~75° F

Jeff Studenka of the Division of Water Quality (DWQ) visited the reclaimed Crandall Canyon and Star Point Mine sites as part of DOGM's Bond Release Inspection process. Representatives from Plateau Mining, DOGM, BLM and OSM were also present.

FACILITY DESCRIPTION

<u>Locations</u>: Crandall Canyon ~5 miles North of Helper off US 6 in Carbon County, UT.

Coordinates: latitude 39° 45' 47.46", longitude 110° 53' 59.21"

Star Point Mine site is in Wattis off Hwy. 122 in Carbon County, UT.

Coordinates: latitude 39° 31' 43.28", longitude 111° 01' 16.30"

<u>Flow Info</u>: No flow data since Crandall Canyon's temporary Outfall 016 in 2007. All outfalls have either been reclaimed or transferred to other owners and the potential to discharge has been obviated.

<u>Receiving waters</u>: Crandall Canyon Creek (dry) → Price River

Serviceberry Creek (dry) → Price River drainage

Site Info: Former underground coal mining operation facilities. The mining operations are no longer present and reclamation activities were completed several years ago. Outfall 016 was added to the existing UPDES general permit coverage, via a permit modification effective April 16, 2007, to provide for the temporary dewatering of the #2 Mine Shaft in Crandall Canyon, which subsided several hundred feet in November 2006 and subsequently filled with ground water. A pump was placed into the mine shaft water column and was pumped out at a rate of ~300 gpm and into the natural canyon drainage. Dewatering operations were completed in July 2007 and the shaft was safely backfilled and the area reclaimed once again by spring of 2008. Outfall 016 is no longer in place; the potential to discharge obviated and thus has been inactivated along with previous outfalls.

INSPECTION SUMMARY

There were no deficiencies noted during the previous inspection of these areas for follow up (CEI performed 8-26-2008). A tour of the facility included observing the reclaimed areas of both the Crandall Canyon and Start Point mine sites. The receiving water drainages were also observed and a few photos were collected for the file, as this will likely be the final DWQ inspection of these areas.

DEFICIENCIES

No deficiencies with respect to the UPDES permit were observed during the inspection.

REQUIREMENTS

None

AMC-Willow Creek Hine Reclamation Sites (UTG040012)

58		Photo Log			
Photo Number	File Name	Description	Date Tim		Photographer
(1)	_	Crandall Canyon Mine Shaft #2 area	6-8	-10	72
(2)		Crandall Conyon temp. Sed. pond area	6-	F-10	σs
		as reclaimed in 2008			
3	_	Overview of reclaimed sed pond	6-	8-10	55
4		of Mine shaf#2 area in Crondall Conyon			
(1)	~	UPStream in dry channel of 3	6-	8-10	JZ
5		Former Star Point Mine site as	6-8	-(0	JZ
		reclaimed, watts, ut.			
6	_	Reclaimed areas looking down	6	-10	55
		stream in waters, or			
0	_		(a-	5-10	J
		on South Side of road, waths, or			
(8)	_	Recently reclaimed areas facing West	(e-	8-18	JI
		from South side of road in Watth		1	
- +	-0M				
6				4	
					H, M. T.
				8	

PMC-Willow Creek Mine Redamation Sites (UTG040012)













